

Table of contents

- F8098 F8 test error, F8022 error reaction

F8098 F8 test error, F8022 error reaction

Using "Axis shutdown: Activation of test errors" (0x2870:04 / P-0-0257 / --), this error was triggered for test purposes to check the controlled deceleration of an axis.

Cause	Remedy
The value "0x0008" was written to "Axis shutdown: Activation of test errors" (0x2870:04 / P-0-0257 / --)	1. Write the value "0" to "Axis shutdown: Activation of test errors" (0x2870:04 / P-0-0257 / --) 2. Reset error

See also Error reaction

► [Attributes](#)