

Table of contents

■ E2132 Touch probe input I_1: Bouncing detected

E2132 Touch probe input I_1: Bouncing detected

The signal at probe input I_1 bounces, i.e. the evaluation function has detected more than one edge.

Cause	Remedy
The signal at probe input I_1 bounces, the evaluation function has detected multiple edges.	Use a bounce-free probe
This results in the following behavior:	
 Only the last detected edge is evaluated. The edge counters may register more edges than occurred probe events. 	

► Attributes

Bosch Rexroth AG Page 1