

## Table of contents

- SMO error reaction: F7 tolerance time (0x315E:03 / P-0-3263.0.7 / --)

## SMO error reaction: F7 tolerance time (0x315E:03 / P-0-3263.0.7 / --)

### Function

The parameter defines the maximum time provided in which the drive has to be at a standstill with the “error response F7”. Otherwise, the error message “F8350 Timeout deceleration” is generated.

See also Safely monitored delay (SMD)