

Table of contents

E2818 Phase failure

E2818 Phase failure

The failure of a mains phase was detected that lasted longer than the tolerated phase failure time.



In the case of phase failure, the device keeps working for two seconds with reduced feed-in power (approx. 60%).

If the phase failure lasts longer than 2 seconds, the <u>error</u> F2818 is generated.

Cause	Remedy
Mains circuit breaker defective	Replace mains circuit breaker
Incorrect wiring	Check and correct wiring

► Attributes

Detailed diagnostics

00450308

Bosch Rexroth AG Page 1